



EXHAUST MANIFOLD REPAIR

ROSINA 200 SERIES PROKIT Ford Int'l Diesel 6.4L Turbo "Y" Pipe

ProMAXX A complete solution for a difficult repair. Rosina™ is precision-engineered to provide an easy and hassle-free solution to repair the turbo charger Y-Pipe mounting on the Ford 6.4L Int'l Diesel engine without replacing it! *Rosina was engineered to cut repair time from over an hour per stud to less than 15 minutes.*

Key Drivers:

- Save up to 4 hours of shop time
- Increase service ledger profitability
- Repairs the Turbo Charger to better than new condition
- Does not require a Helicoil insert
- Limited Lifetime Warranty
- Made in U.S.A.



Ford Int'l Diesel 6.4L Turbo "Y" Pipe



Now with replaceable bushings for even faster repairs



Remove broken screw extractors without removing the cylinder head

